

RECEIVED

FEB 26 1992

DIVISION OF  
OIL GAS & MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/91 To (mo./yr.) 1/92
2. DOGM File Number: M / 041/ 008
3. Mine Name: Jensen Quarry
4. Mineral(s) Mined: Gypsum
5. Legal Description (Location of Lands Affected):  
1/4, 1/4, Section 22, Township 22 S, Range 1 W  
1/4, 1/4, Section 32, Township 22 S, Range 1 W  
1/4, 1/4, Section 15, Township 22 S, Range 1 W
6. Name of Operator or Company: UNITED STATES GYPSUM COMPANY
7. Permanent Address: Corporate: 101 S. Wacker Dr., Chicago, IL 60606  
Plant: P.O. Box 160, Sigurd, Utah 84657

8. Company Representative (or designated operator):

Name: David M. Hollingshead

Title: Quarry Manager

Address: P.O. Box 160, Sigurd, UT 84657

Phone: (801) 896-4484

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 117,506 Tons

3. How much new or additional acreage was affected during past year? 2.69

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

There was 44,621 cu. yds of shale stripped with a dozer to expose  
gypsum beds in ten pits. A new section of haul road was added to  
access the Line quarry and Bowl quarry.

5. How much acreage was reclaimed during past year? 2.75

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

The 2.75 acre area at C-7 quarry was graded with a dozer.  
Highwalls were broken over where possible to an angle less  
than the angle of repose.

7. What is the total disturbed acreage at years end? 116.42

8. Briefly summarize mining and reclamation planned for the upcoming year.

There will be approximately 35,000 cu. yd. stripped resulting  
in less than 3.00 acres disturbed. Boulder salvage from the  
C-7, C-4, Crescent and 5-B areas will continue. The C-7, 5-B,  
and C-2 areas will be graded and seeded in 1992 for a total  
acreage of 6.25.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

David M. Hollingshead

Title of Operator:

Quarry Mgr.

Signature of Operator:

David M. Hollingshead

Date:

2/24/92

jb  
MR-AR